

Condition Assessment/Economic Analysis – 2003  
ECI/HYER, Inc. Architecture Interiors, Development  
Page Subject

i	FWA history and background
	Brief description of Alterations to Hangars 2 and 3
1	Hangar bay door overhang description and dimensions
6	Structural Description of Overhangs
9	Structural Information on Overhangs – material and makeup
13	Overhang Condition Assessment – decking, sheathing, trusses
15	Evaluation Results – Overhangs
17	Recommendations – Overhangs
20	Pocket Walls – description, dimensions
22	Pocket Walls – condition assessment and evaluation
27	Lateral System/Framing – Overhangs
29	Walls (vertical force resisting elements) – overhangs
42	Exterior Envelope description – discussion of overhangs and exterior stairs
44 – 48	Recommendations for Repairs to Hangars – overhangs, catwalks
50-51	Exterior Stairs – Emergency Egress

Photos/Drawings

A10-H3 –A13-H6	Condition of Overhangs and catwalks
A3.1	Elevation of Hangar 2 showing recommendations