

Disposition of Hangars 2 and 3: Photographs



Table of Contents

- 1) Current Conditions**
- 2) Historic Photos**
- 3) Hangar 2 Interior**
- 4) Hangar 3 Interior**
- 5) Truss Inspection**
- 6) Hangar 2 Fire**

1) Current Conditions

Hangar 2, West elevation – May 5, 2011



Hangar 2, West elevation – October 31, 2011



Hangar 3, Northwest oblique – October 31, 2011



2) Historic Images

Hangars 2 and 3, Framing – 1942



Hangar 3 – circa 1946 (photo by John Mertz)



Hangar 3 with parked B-29s – circa 1946 (photo by John Mertz)



Hangar 2 with parked F-82 Twin Mustang – circa 1949



Birchwood hangar interior with F-82 undergoing maintenance – circa 1949



3) Hangar 2 Interior

Hangar 2, Split and reinforced support column – June 17, 2010



Hangar 2 Interior, Cut cross brace – June 17, 2010



Hangar 2, Detail of trusses – June 17, 2010



4) Hangar 3 Interior

Hangar 3, Detail of trusses from the second floor – July 8, 2010




Hangar 3, Detail of catwalks and hangar ceiling – July 8, 2010



Hangar 3, Detail of hangar trusses – July, 8, 2010



Hangar 3, Detail of cross braces – July 8, 2010



5) Truss Inspection

Hangar 2, Split truss top chord – June, 28, 2007



Hangar 2, Broken truss chord – June 28, 2007



Hangar 2, Loose roof slats – June 28, 2007




Hangar 2, Missing cross brace – June 28, 2007




Hangar 2, Split cross brace connection – June 28, 2007




Hangar 2, Split truss connection – June 28, 2007




Hangar 3, Missing cross brace – June 28, 2007




Hangar 3, Severe column split – June 28, 2007




Hangar 3, Split member and localized buckling – June 28, 2007




Hangar 3, Split member – June 26, 2007



Hangar 3, Split truss chord – June 26, 2007



Hangar 3, Truss connection split – June 26, 2007



6) Hangar 2 Fire

Hangar 2 fire from Meridian Road – February 17, 2011



Detail of flames – February 17, 2011



Exposed roofline trusses, post fire – February 19, 2011



Fire Marshall inspection photo– February 19, 2011



Fire Marshall inspection photo – February 19,



Fire Marshall inspection photo – February 19, 2011



Fire Marshall inspection photo – February 19, 2011

